

AUTOSERVE by



Car Next Door Vehicle Inspection Form

RACT AutoServe

ABN 49 158 958 911

Head Office: 179-191 Murray Street Hobart 7000

Tel. 1300 127 684

DRIVER DETAILS

OWNERS FULL NAME

Harpreet Singh

EMAIL ADDRESS

hs7504451@gmail.com

PHONE NUMBER

0470281121

DATE

06/12/2023

VEHICLE DETAILS

VEHICLE MILEAGE

142845

VEHICLE MAKE

Ford

OF DOORS

4

REGISTRATION

L24JP

VEHICLE MODEL

Focus

INSPECTOR NAME

Liam Grundy

MODEL YEAR

2011

INSPECTION ADDRESS

AUTOSERVE - HOBART

INSPECTOR SIGNATURE

12 MONTH reinspection?

No

INTERIOR

INTERIOR SMELLS / ODOURS

PASS

UPHOLSTRY DAMAGED

PASS

5 - 8 TOTAL SEATING CAPACITY

PASS

DASH GAUGES & WARNING LIGHTS

PASS

INTERIOR CLEAN AND TIDY

PASS

AIR CONDITIONING FUNCTION

PASS

AUTOSERVE by



Car Next Door Vehicle Inspection Form

RACT AutoServe

ABN 49 158 958 911

Head Office:179-191 Murray Street Hobart 7000

Tel.1300 127 684

EXTERIOR

4 DOOR VEHICLE

PASS

BODY DAMAGE

PASS

EXHAUST NOISE, SMOKE OR EMISSIONS

PASS

WINDSCREEN

PASS

WINDSCREEN WIPER FUNCTION

PASS

ALL WINDOWS FUNCTION

PASS

ENGINE BAY

NOISES

PASS

LEAKS, INDICATING A FAULT

PASS

BELTS AND PULLEYS

PASS

UNDER BODY

GENERAL UNDERBODY CONDITION

PASS

EXHAUST

PASS

AUTOSERVE by



Car Next Door Vehicle Inspection Form

RACT AutoServe

ABN 49 158 958 911

Head Office: 179-191 Murray Street Hobart 7000

Tel. 1300 127 684

PHOTOS

INSTRUMENT CLUSTER



VEHICLE EXTERIOR



VEHICLE EXT WITH NUMBER PLATE



INTERIOR

DAMAGE - IF ANY

IF VEHICLE FAILS

PROVIDE COMMENTS

AUTOSERVE by



Car Next Door Vehicle Inspection Form

RACT AutoServe

ABN 49 158 958 911

Head Office: 179-191 Murray Street Hobart 7000

Tel. 1300 127 684

INSPECTION PASS / FAIL

PASS / FAIL

PASS

Inspection number AB.....

2882

STATE GROWTH INSECTION SHEET

INSPECTION SHEET



INSPECTION REPORT

Small Passenger Vehicle

SPV2882

Registered Operator

Accreditation Number

419295567

Operator Name

HARPREET SINGH

Vehicle Inspected At (Location)

HOBART

Reason for inspection

Hire and Drive

Licence plate number

Vehicle Details

Registration Number

L24JP

Month and Year of Manufacturer

11 / 2011

VIN Number / Chassis

WF0KXXGCBKBJ12991

Modification plate no.

Make

FORD

Model

FOCUS

Odometer

142845

Number Of Axles

2

Seating Capacity:

Manufactured	Child	Adult	Standing
5	0	0	0

Inspection Report

First Inspection Result

PASS

Second Inspection Result

Label No.

58144

Next Inspection Month and Year

12 / 2024

I LIAM N GRUNDY

inspected the above vehicle on 06/12/2023 09:47 AM and certify that it complies with the requirements of the relevant Vehicle Inspection Manual

V.E. No.

VE1728

A.I.S. Number

S115

AUTOSERVE by



Car Next Door Vehicle Inspection Form

RACT AutoServe

ABN 49 158 958 911

Head Office: 179-191 Murray Street Hobart 7000

Tel. 1300 127 684

DISCLAIMER

- RACT Autoserve inspection is not a guarantee or warranty and is valid only at the time of inspection.
- This report does not purport to be a roadworthy inspection, but rather a special purpose vehicle inspection with a focus on safety and comfort.
- This inspection is VISUAL only. No removal of parts or components is undertaken during the inspection process

- The inspection report is prepared for the person named on the report and not for use by any third party.
- Limited or no road test performed
- This report serves to identify any visually detected problems however dismantling components may be subsequently required so as to provide a more accurate diagnosis

RACT AutoServe does NOT check the following items

- | | | |
|---------------------------|----------------------------------|---|
| -Timing Belts | -Alarm / security systems | -Automatic switching of wipers and lights |
| -Fuel and Oil consumption | -Navigation equipment / GPS | -Anti-locking braking systems |
| -Trip meters / computers | -Operation of TV / Audio systems | -Compression of engine |